Listed below are some of our recent projects on Load Capacity & Condition Monitoring of Bridges These are generally our Australian Projects

Year	Client	Location
20	19	
	Bendigo GCC	Load capacity testing & inspection of 5 concrete bridges, Bendigo, Vic
	RMS-NSW	Load capacity testing & inspection of Korns concrete bridge, NSW
	Mulgoa Excavation Bendigo GCC	Load capacity testing & inspection of concrete bridge in Mulgoa, NSW Load capacity testing & inspection of 4 timber bridges, Bendigo, Vic
	Bendigo GCC Bendigo GCC	Load capacity testing & inspection of 4 timber bridges, Bendigo, Vic
	Narrabri Council	Load capacity testing & inspection of 3 long post tensioned concrete bridges,
		Narrabri, NSW
	Vic Track	Reverse engineering design of concrete railway bridge, Wangaratta, Vic
Year	Client	Location
20	18	
	Loddon Shire	Load capacity testing & inspection of a timber composite bridge, Vic
	Bayside CC	Load capacity testing & inspection of an RC bridge, Vic
	Bendigo GCC	Load capacity testing & inspection of 6 concrete/steel bridges, Vic
	I-Cubed	Load capacity testing & inspection of a timber bridge, Qld
	Coffs Harbour	Load capacity testing & inspection of 3 bridges, timber & RC, NSW
	Victrack	Load capacity testing & inspection of a timber/steel bridge at Rutherglen, Vic
	Narranderra SC	Load capacity testing & inspection of an RC bridge, NSW
	Yarra Ranges	Load capacity testing & inspection of cable stay bridge, Vic
	Victrack	Load capacity testing & inspection of RC bridge, Vic
	Bendigo GCC	Load capacity testing & inspection of brick arch bridge, Vic
	Victrack	Load capacity testing & inspection of 3 brick arch bridges, Vic
	Bendigo GCC	Load capacity testing & inspection of 3 composite concrete/steel bridges, Vic
	Moira Shire	Load capacity testing & inspection of a timber bridge, Vic
Year	Client	Location
20		Location
	Moira Shire	Load capacity testing & inspection of a timber bridge, Vic
	Tenterfield Shire	Load capacity testing & inspection of 17 number of timber bridges. NSW
	Victrack	Load capacity testing & inspection of a composite timber/steel bridge. Vic
	Tamara Shire	Load capacity testing & inspection of 2 concrete bridges. NSW
	Bendigo GCC	Load capacity testing & inspection of 3 concrete bridges, Vic
	Hilltops SC	Load capacity testing & inspection of 14 bridges, for NSW future roads
	Lockhart SC	Load capacity testing & inspection of 11 bridges, for NSW future roads
	Woollondilly SC	Load capacity testing & inspection of 3 very large concrete bridges. NSW
	N Grampians SC	Load capacity testing & inspection of two composite bridges. Vic
	GHD Cairns	Load capacity testing & inspection of a long timber bridge. Qld
	Hilltops SC	Load capacity testing & inspection of 14 no bridges. NSW
	Victrack	Capacity testing & inspection of 13 brick arch bridges, Kyneton-Bendigo, Vic
	Victrack	Load capacity testing & inspection of a timber bridge in Gippsland. Vic
	VIOLICON	Load departs to string a more of or a timber bridge in dippolarid. We

Year	Client	Location
201	6	
	Tamworth RCC	Capacity testing & inspection of 80 concrete & timber bridges for compliance for HML. NSW
	Victrack	Capacity testing & inspection of 6 concrete bridges for potential upgrades.
	Weddin SC	Load capacity testing & inspection of a timber bridge. NSW
	Bendigo GCC	Load capacity testing & inspection of 3 timber bridges. Vic
	TMG	Load capacity testing & inspection on composite concrete & steel bridge. Vic
	Bendigo GCC	Load capacity testing & inspection on Nolan St bridge, composite steel and concrete bridge. Vic
	Gwydir SC	Load capacity testing & inspection of 3 number concrete bridges. NSW
	Woolondilly SC	Capacity testing & inspection of large concrete bridges +200m after flood damage. NSW
	TGM	Capacity testing & inspection of Heritage Concrete & Masonry bridge. Vic
	Midcoast SC	Capacity testing & inspection of 19no timber bridges for NSW future projects
	REROC	Load capacity testing & inspection of 33 no concrete/steel bridges for
		NSW future projects, NSW
	Bendigo GCC	Load capacity testing & inspection of 3 no timber bridges. Vic
Year	Client	Location
201	5	
	Colac Otway	Load capacity testing & inspection of 2 no timber bridges. Vic
	Moira Shire	Load capacity testing & inspection of a timber composite bridge, Vic
	VicTrack	Capacity testing & inspection on a concrete & steel composite bridge, Vic
	Moira Shire	Load capacity testing & inspection of a timber & steel composite bridge, Vic
	Yarra Ranges Shire	Capacity testing & inspection of a concrete & timber composite bridge, Vic
	VicTrack	Capacity testing & inspection of a very long concrete & steel composite bridge, Vic
	VicTrack	Load capacity testing & inspection of a 300 metre footbridge, Vic
	Coolamon Shire	Load capacity testing & inspection of 3 composite bridges for Mass Limit Loadings, NSW
	Woolondilly Shire	Capacity testing & inspection of 180m long Blaxland concrete bridge, NSW
	VicTrack	Load capacity testing & inspection of 2 steel bridges damaged by truck, Daylesford, Vic
	Cassowary Coast Council	Capacity testing & inspection of 3 timber/concrete composite bridges, QLD
	Yarra Ranges Shire	Load capacity testing & inspection of steel truss bridge, Vic
Year	Client	Location
201	4	
	Horsham City Council	Load capacity testing & inspection on Norton Creek Bridge, Vic
	Sydney Water	Load capacity testing & inspection on Bargo River Bridge, NSW
	Bendigo City Council	Load capacity testing & inspection on four timber bridges, Vic
	Weddin Shire Council	Load capacity testing & inspection on a large concrete bridge, NSW
	VicTrack	Capacity testing & inspection to Stawell Station exit concrete bridge, Vic
	Coffs Harbour City Council	Load capacity testing & inspection on two timber bridges, NSW
	Baw Baw Shire	Capacity testing & inspection on 13 composite timber/concrete bridges, Vic
	Gold Coast City Council	Load capacity testing & inspection on 3 large & long concrete bridges, QLD

	VicTrack	Capacity testing & inspection of the Dimboola Station timber footbridge, Vic
	Tamworth Regional Council	Capacity testing & inspection of 11 composite steel/concrete bridges, NSW
	Bendigo City Council	Full Level 3 Inspection of three timber bridges, Vic
	Baw Baw Shire	Load capacity testing & inspection of a timber/steel composite bridge, Vic
Year	Client	Location
2013		Location
2010	VicTrack	Load capacity testing & inspection for 3 composite concrete/steel bridges, Vic
	Bendigo City Council	Load capacity testing & inspection for 3 composite steel/concrete bridges, Vic
	Tamworth Regional Council	Load capacity testing & inspection for 20 bridges, Tamworth, NSW
	GHD Cairns	Load capacity testing & inspection on a composite bridge, Cairns, Qld
	Moyne Shire	Load capacity testing & inspection for 16 bridges, Warrnambool, Vic
	Gold Coast City Council	Load capacity testing & inspection for a timber bridge, Gold Coast, Qld
	Moyne Shire	Load capacity testing & inspection on 5 composite bridges, Vic
	Wagga Wagga City Council	Load capacity testing & inspection on the Eunony concrete Bridge, NSW
	Taree City Council	Capacity testing & inspection on a large timber bridge after repairs, NSW
	Kingston City Council	Load capacity testing & inspection on two concrete bridges, Vic
	Tangoton Oity Counon	Load dapasity todaing a inspection on two controls bridges, vie
Year	Client	Location
2012		
	VicTrack	Load capacity testing & inspection on a concrete bridge, Vic
	Forbes Shire	Retest of historic bridge after recommended repairs, Vic
	Port Macquarie Hastings	Capacity testing & inspection of Stingray Bridge for repair strategy, NSW
	Colac Otway Shire	Capacity testing & inspection of three composite timber/steel bridges, Vic
	GHD Cairns	Load capacity testing & inspection of Tully Falls concrete Bridge, Qld
	Boorowa Shire	Load capacity testing & inspection of a composite timber/steel bridge, NSW
	Coolamon Shire	Load capacity testing & inspection of two large composite bridges, NSW
	Kingston City Council	Load capacity testing & inspection of 3 concrete bridges for serviceability, Vic
Year	Client	Location
2011		
	Wagga Wagga City Council	Retest of two concrete bridges after repairs, NSW
	Cassowary Coast Council	Capacity testing & inspection of 22 Bridges after tropical cyclone "Yasi", Qld
	Loddon Shire	Load capacity testing & inspection of 5 concrete bridges after flooding, Vic
	South Gippsland Shire	Load capacity testing & inspection of 2 concrete bridges for rail trail, Vic
	Gold Coast City Council	Load capacity testing & inspection of 4 concrete bridges after floods, Qld
	Gunnedah Shire	Capacity testing & inspection of 13 concrete bridges for load & integrity, NSW
	Gold Coast City Council	Load capacity testing & inspection of 7 timber bridges, Qld
	Colac Otway Shire	Load capacity testing & inspection of 4 bridges, Vic
	City of Greater Bendigo	2 bridge retests after repairs, Vic
	Wagga Wagga City Council	6 bridges tested after recommended repairs from prior inspections, NSW
	Tamworth Regional Council	Load capacity testing & inspection of 21 bridges and recommendations after
		floods including a historic Allan Truss Bridge, NSW
	City of Greater Bendigo	4 bridges for reinspection after initial testing over 5 years ago, Vic
	Wollondilly Shire Council	Load capacity testing & inspection of 5 bridges for repairs, NSW
	Boorowa Shire	Load capacity testing & inspection of large six span timber bridge, NSW
		•

Year	Client	Location
2010		
	South Gippsland Shire	Load capacity testing & inspection on timber/steel composite bridge, Vic
	South Gippsland Shire	Load capacity testing & inspection, plus design & supervision on bridge, Vic
	Baw Baw Shire	Load capacity testing & inspection on three composite bridges, Vic
	Wagga Wagga City Council	Load capacity testing & inspection on Brooklyn Lane bridge, NSW
	South Gippsland Shire	Re-checking 2 bridges for loading capacities, after desk top studies
		closed the bridges. We retested & now repaired for T-44 trucks, Vic
	Wagga Wagga City Council	Load capacity testing & inspection for 14 bridges after severe flooding, NSW
	Bendigo City Council	Capacity testing & inspection of 4 bridges including Historic Arch bridge, Vic
	South Gippsland Shire	Capacity testing & inspection of composite steel and concrete bridge, Vic
	Ararat Rural City Council	Load capacity testing & inspection of 8 bridges, steel, timber & concrete, Vic
	South Gippsland Shire	Full inspection of bridge, design & supervision of repairs, Vic
	VicTrack Access	Re-testing of large cast iron bridge after previous desk top study
		recommended new bridge. Bridge reopened after minor repairs, Vic
	GHD Cairns	Third testing for Jubilee Bridge in Innisfail, bridge closed and new
		bridge to be constructed, Qld
	VicTrack Access	Load capacity testing & inspection of 4 timber bridges with design & repair
		supervision, Vic
	Wagga Wagga City Council	Capacity testing & inspection of 7 composite steel & concrete bridge, NSW
	Gunnedah Shire	Load capacity testing & inspection of timber composite bridge, NSW
	Port Macquarie Hastings	Capacity testing & inspection of 11 bridges, composite steel & timber, NSW
	Port Macquarie Hastings	Load capacity testing & inspection of Historic Kindee Bridge, a unique timber
		suspension bridge, NSW
	VicTrack Access	Capacity testing & inspection, design & supervision of a timber bridge, Vic
	Ararat Rural City Council	Capacity testing & inspection of a bridge where an accident had occurred,
		with re-design recommendations, Vic
	Harden Shire	Capacity testing & inspection of 3 bridges from our results of our previous
		level 2 inspections, NSW
	Forbes Shire	Load capacity testing & inspection of an Historic timber structure, NSW
	South Gippsland Shire	Load capacity testing & inspection of a timber bridge, Vic
	City of Greater Bendigo	Load capacity testing & inspection of 3 timber bridges for rail trail, Vic
	Wagga Wagga City Council	Capacity testing & inspection of 20 composite timber/concrete bridges after
		severe flooding, NSW
	VicTrack Access	Load capacity testing & inspection, design & supervision of 3 bridges, Vic
Year	Client	Location
2009		
	Victrack	Structural Testing of Historic Merri River bridge at Dennington, Vic
	Wagga Wagga City Council	Consultant for rescue for partially failed 1895 AlanTr uss Bridge (Hampden
		Bridge). Successfully restored & now to be used as a Rail Trail, NSW
	Armidale Dumaresq Shire	Capacity testing of two composite bridges for load rating, etc, NSW
	City of Greater Bendigo	Load capacity testing & inspection of 5 bridges with various construction, Vic
	VicTrack	Load capacity testing & inspection of 10 bridges, all timber composites &
		5 requiring repair specifications & full site control of the repairs, Vic
	Colac Otway Shire	Load capacity testing & inspection with mainly timber bridges, Vic
	City of Coffs Harbour	Repair strategy for all timber bridges, NSW
	City of Colle Halbour	Topan shategy for an uniber bridges, NOW

Wagga Wagga City Council	Kapooka Historic Rail Arch Bridge, capacity inspections with discussions with various parties for the repairs to the bridge, NSW
Wellington Shire	Load capacity testing & inspection of the Lake Glenmaggie Historically listed
	bridge over Lake Glenmaggie. Preparation of options for repairs for
	the timber truss section of the bridge, Vic
GHD Cairns	Retesting of Historic Jubilee bridge, Innisfail to determine rate of loss
	of load capacity after initial full testing inspection of bridge in 2003, Qld
Greater Taree Council	Load capacity testing & inspection of 7 timber bridges, NSW
Colac Otway Shire	Re-testing of two timber bridges after repairs for load testing, Vic
South Gippsland Shire	Capacity testing & inspection on 3 composites concrete/steel bridges, Vic
Port Macquarie Hastings	Load capacity testing & inspection on 10 bridges, timber & composites, NSW
Loddon Shire	Capacity testing & inspection on 5 bridges, timber composites & concrete, Vic
South Adelaide Hills	Load capacity testing & inspection on a steel/concrete composite bridge, SA
Greater Taree Council	Load capacity testing & inspection on a timber/steel composite bridge, NSW
VicTrack	Load capacity testing & inspection on 4 timber/steel composite bridges, Vic
North Grampians Shire	Load capacity testing & inspection on 15 bridges, timber, steel & concrete, Vic
Wellington Shire	Load capacity testing & inspection on Glenmaggie bridge for Heritage, Vic
Greater Taree Council	Re-testing timber truss bridge after repairs, NSW

Year	Client	Location
20	08	
	VicTrack	Load capacity testing & inspection of a rail overbridge, Huntly, Vic
	City of Greater Bendigo	Load capacity testing & inspection of three concrete bridges, Vic
	Wagga Wagga City Council	Load capacity testing & inspection of seven span historic bridge, NSW
	VicTrack	Load capacity testing & inspection of seven timber bridges including design,
		production of drawings and project supervision, VIC
	Wagga Wagga City Council	Load capacity testing & inspection of eight span concrete bridge, NSW
	City of Coffs Harbour	Load capacity testing & inspection of a five span bridge, Coffs Harbour, NSW
	Inverall Shire	Load capacity testing & inspection of three multi span bridges, Inverall, NSW
	Narrabri Shire	Capacity inspection, testing & repair requirements of bridges, Narrabri, NSW
	Musswellbrook Council	Capacity inspection & testing of 4 multispan bridges, Musswellbrook, NSW
	City of Coffs Harbour	Load capacity testing & inspection of 6 bridges, NSW
	Baw Baw Shire	Load capacity testing & inspection of three bridges, Baw Baw, Vic
	Oberon Shire	Load capacity testing & inspection of one bridge, Oberon, NSW
	City of Greater Bendigo	Load capacity testing & inspection of four multi span bridges, Bendigo, Vic
	Melton Shire	Capacity testing & inspection of a bridge for CFA requirements, Melton, Vic
Voor	Client	Location

#### Year Client Location

### 2007

Central Goldfields Shire

Armidale Dumaresq Shire

Gundagai Shire

Load capacity testing & inspection of 5 bridges, timber, steel & concrete, Vic

Load capacity testing & inspection of five bridges, all types, NSW

Load capacity testing & inspection of Historic Bridge, NSW

Yarra Ranges Council

Load capacity testing & inspection of two timber bridges, Vic

Moyne Shire

Load capacity testing & inspection of five bridges, Vic

Weddin Shire

Load capacity testing & inspection of an Historic Bridge, NSW

Nambucca Heads Shire

Load capacity testing & inspection of an Historic Bridge, NSW

Mitchell Shire	Load capacity testing & inspection of two critical bridges, Vic
City of Greater Bendigo	Load capacity testing & inspection of four bridges in critical condition, Vic
Colac Otway Shire	Load capacity testing & inspection of three bridges, Vic
City of Greater Bendigo	Load capacity testing & inspection of four bridges, Vic
Wellington Shire	Load capacity testing & inspection of 9 bridges, Vic
Wellington Shire	Load capacity testing & inspection of six bridges due to flood damage, Vic
Urana Shire	Load capacity testing & inspection of seven concrete bridges, NSW
Moyne Shire	Load capacity testing & inspection of four bridges, Vic
Wellington Shire	Load capacity testing & inspection of four flood damaged bridges, Vic
Yarra Ranges Shire	Load capacity testing & inspection of a single timber bridge, Vic
Wellington Shire	Load capacity testing & inspection of timber bridge, Vic
Gloucester City Council	Load capacity testing & inspection of an Historic Bridge, NSW
City of Coffs Harbour	Load capacity testing & inspection of three bridges, NSW
Baw Baw Shire	Capacity testing & inspection of eight bridges of various constructions, Vic
City of Greater Bendigo	Load capacity testing & inspection of three bridges, Vic

Year	Client	Location

6	
Wellington Shire	Load capacity testing & inspection of 22 bridges, Vic
City of Coffs Harbour	Load capacity testing & inspection of an Historic Timber Bridge, NSW
Wellington Shire	Capacity inspection and specification for repairs of Wheelers bridge, an historic
	Monash designed bridge & concrete arch, Vic
Moorabool Shire	Load capacity testing & inspection of six bridges of mixed composites, Vic
South Gippsland Shire	Testing of two timber bridges with critical loading requirements, Vic
City of Coffs Harbour	Load capacity testing & inspection of bridge after recommended repairs, NSW
Tamworth Regional Council	Load capacity testing & inspection of five bridges with mixed composites, NSW
Wagga Wagga City Council	Load capacity testing & inspection of seven mixed composite bridges, NSW
Gundagai Shire	Load capacity testing & inspection of Historic bridge with critical loadings, NSW
Kyogle Council	Load capacity testing & inspection of 5 timber bridges for fire trucks, NSW
Tenterfield Shire	Load capacity testing & inspection on bridge, critical for school bus, NSW
Taree City Council	Capacity inspection of two timber bridges with specifications for repairs.
	Retested after repairs, now suitable for T-44 loadings, NSW
Moyne Shire	Specifications for three bridges with site supervision, Vic
Moyne Shire	Load capacity testing & inspection of 5 bridges for safe loadings of trucks, Vic
Moira Shire	Load capacity testing & inspection of Historic Hancocks Bridge, Vic
Tamworth Regional Council	Capacity testing of 8 bridges for repairs rather than replacement due to lack
	of funding, NSW
Wellington Shire	Completion of a total of 95 bridges with a 2.5 inspections, Vic
Murrumbidgee Irrigation	Capacity testing & inspection of precast concrete bridge with cracking, NSW
City of Greater Bendigo	Load capacity testing & inspection of 7 bridges of mixed construction, Vic
Wagga Wagga City Council	Capacity test of an 1895 Allan Truss Hampden Bridge after partial
	failure & specification of repairs, NSW
City of Coffs Harbour	Load capacity testing & inspection of two very long timber bridges, NSW
Moyne Shire	Capacity testing & inspection of 12 bridges for safe passage of timber trucks, Vic
Gloucester City Council	Load capacity testing & inspection of a 50m timber/steel composite bridge, NSW
Taree City Council	Capacity test & inspection of long timber bridge, upgrade for T-44 usage, NSW

Year	Client	Location
2005		
	Central Goldfields Shire	Load capacity testing & inspection of 6 composite bridges, Vic
	Moyne Shire	Load capacity testing & inspection of five composite bridges, Vic
	Moyne Shire	Capacity testing of concrete bridge, plus foundations of timber bridge, Vic
	Central Goldfields Shire	Specifications for two bridge repairs, Vic
	Pyrenees Shire	Load capacity testing & inspection of three composite bridges, Vic
	Palerang Council	Capacity testing & inspection of two multi span bridges near the ACT, NSW
	Tenterfield Shire	Load capacity testing & inspection of two timber bridges, NSW
	Wagga Wagga City Council	Capacity testing of six timber & timber composite bridges, NSW
	Central Goldfields Shire	Advisor to Council on cost effectiveness of repairs to 2 bridges, NSW
	Moira Shire	Load capacity testing & inspection of five composite steel & timber bridges, Vic
	Ballina Shire	Capacity testing & inspection of an 8 span composite steel/timber bridge, NSW
	Moira Shire	Advise on urgent repairs to two bridges closed to traffic, Vic
	Colac Otway Shire	Capacity testing of 9 span timber bridge over a river after partial repairs, Vic
	Corangamite Shire	Capacity testing to determine load rating of concrete bridge, Vic
	Wellington Shire	Investigation of 20 bridges using our Level 2.5 inspections, Vic
	Baw Baw Shire	Load capacity testing & inspection of 3 composite steel & timber bridges, Vic
	City of Coffs Harbour	Load capacity testing & inspection of 3 composite steel & timber bridges, NSW
	Tamworth Regional Council	Load capacity testing & inspection of timber bridges, NSW
	Armidale Dumaresq Shire	Load capacity testing & inspection of three timber bridges, NSW
	Ararat Rural City Council	Load capacity testing & inspection of two composite steel & timber bridges, Vic
	Moyne Shire	Capacity testing of 13 composite steel, timber concrete & masonry bridges, Vic
Year	Client	Location
Year 2004		Location
		Location  Load capacity testing & inspection of three suspension bridges, Vic
		Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic
	Alpine Shire Central Goldfields Shire Wellington Shire	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic
	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic
	Alpine Shire Central Goldfields Shire Wellington Shire	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic
	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic
	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron
	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire GHD Cairns	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron Gorge, Cairns, Qld
	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron
2004	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire GHD Cairns Baw Baw Shire	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron Gorge, Cairns, Qld Capacity investigation of 3 composite concrete, steel & timber bridges, Moe, Vic
2004 Year	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire GHD Cairns Baw Baw Shire Client	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron Gorge, Cairns, Qld
2004	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire GHD Cairns Baw Baw Shire Client	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron Gorge, Cairns, Qld Capacity investigation of 3 composite concrete, steel & timber bridges, Moe, Vic Location
2004 Year	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire GHD Cairns Baw Baw Shire Client South Gippsland Shire	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron Gorge, Cairns, Qld Capacity investigation of 3 composite concrete, steel & timber bridges, Moe, Vic  Location  Capacity testing of multi span composite bridge at Agnes, Gippsland, Vic
2004 Year	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire GHD Cairns Baw Baw Shire Client South Gippsland Shire GHD Cairns	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron Gorge, Cairns, Qld Capacity investigation of 3 composite concrete, steel & timber bridges, Moe, Vic  Location  Capacity testing of multi span composite bridge at Agnes, Gippsland, Vic Capacity testing of Jubilee Historic reinforced arch bridge, Innisfail, Qld
2004 Year	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire GHD Cairns Baw Baw Shire Client South Gippsland Shire GHD Cairns Hepburn Shire	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron Gorge, Cairns, Qld Capacity investigation of 3 composite concrete, steel & timber bridges, Moe, Vic  Location  Capacity testing of multi span composite bridge at Agnes, Gippsland, Vic Capacity testing of Jubilee Historic reinforced arch bridge, Innisfail, Qld Investigation of 2 timber composite bridges, Clunes & Leonards, Vic
2004 Year	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire GHD Cairns Baw Baw Shire  Client  South Gippsland Shire GHD Cairns Hepburn Shire City of Coffs Harbour	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron Gorge, Cairns, Qld Capacity investigation of 3 composite concrete, steel & timber bridges, Moe, Vic  Location  Capacity testing of multi span composite bridge at Agnes, Gippsland, Vic Capacity testing of Jubilee Historic reinforced arch bridge, Innisfail, Qld Investigation of 2 timber composite bridges, Clunes & Leonards, Vic Capacity testing 3 reinforced concrete & one reinforced arch bridge, NSW
2004 Year	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire GHD Cairns Baw Baw Shire Client South Gippsland Shire GHD Cairns Hepburn Shire City of Coffs Harbour Wellington Shire	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron Gorge, Cairns, Qld Capacity investigation of 3 composite concrete, steel & timber bridges, Moe, Vic  Location  Capacity testing of multi span composite bridge at Agnes, Gippsland, Vic Capacity testing of Jubilee Historic reinforced arch bridge, Innisfail, Qld Investigation of 2 timber composite bridges, Clunes & Leonards, Vic Capacity testing 3 reinforced concrete & one reinforced arch bridge, NSW Capacity testing of Prospect bridge, a reinforced concrete bridge, Vic
2004 Year	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire GHD Cairns Baw Baw Shire  Client  South Gippsland Shire GHD Cairns Hepburn Shire City of Coffs Harbour Wellington Shire Naracoorte Lucindale Council	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron Gorge, Cairns, Qld Capacity investigation of 3 composite concrete, steel & timber bridges, Moe, Vic  Location  Capacity testing of multi span composite bridge at Agnes, Gippsland, Vic Capacity testing of Jubilee Historic reinforced arch bridge, Innisfail, Qld Investigation of 2 timber composite bridges, Clunes & Leonards, Vic Capacity testing 3 reinforced concrete & one reinforced arch bridge, NSW Capacity testing of Prospect bridge, a reinforced concrete bridge, SA
2004 Year	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire GHD Cairns Baw Baw Shire  Client  South Gippsland Shire GHD Cairns Hepburn Shire City of Coffs Harbour Wellington Shire Naracoorte Lucindale Council Hindmarsh Shire	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron Gorge, Cairns, Qld Capacity investigation of 3 composite concrete, steel & timber bridges, Moe, Vic  Location  Capacity testing of multi span composite bridge at Agnes, Gippsland, Vic Capacity testing of Jubilee Historic reinforced arch bridge, Innisfail, Qld Investigation of 2 timber composite bridges, Clunes & Leonards, Vic Capacity testing 3 reinforced concrete & one reinforced arch bridge, NSW Capacity testing of Prospect bridge, a reinforced concrete bridge, Vic Capacity testing a Monash design reinforced concrete bridge, Vic
2004 Year	Alpine Shire Central Goldfields Shire Wellington Shire South Gippsland Shire Wellington Shire South Gippsland Shire GHD Cairns Baw Baw Shire  Client  South Gippsland Shire GHD Cairns Hepburn Shire City of Coffs Harbour Wellington Shire Naracoorte Lucindale Council	Load capacity testing & inspection of three suspension bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic Capacity testing of four composite & reinforced concrete bridges, Vic Capacity testing & inspection of 6 composite & reinforced concrete bridges, Vic One timber bridge test and repair specifications for six bridges, Vic Load capacity testing & inspection of two reinforced concrete bridges, Vic Capacity testing of 220m long composite steel & concrete bridge, Barron Gorge, Cairns, Qld Capacity investigation of 3 composite concrete, steel & timber bridges, Moe, Vic  Location  Capacity testing of multi span composite bridge at Agnes, Gippsland, Vic Capacity testing of Jubilee Historic reinforced arch bridge, Innisfail, Qld Investigation of 2 timber composite bridges, Clunes & Leonards, Vic Capacity testing 3 reinforced concrete & one reinforced arch bridge, NSW Capacity testing of Prospect bridge, a reinforced concrete bridge, SA

	West Wimmera Shire	Investigation on composite timber bridge, Vic
	Baw Baw Shire	
		Load capacity testing & inspection on 3 composite steel & timber bridges, Vic
	South Grampiana Shire	Investigation on tree damaged concrete bridge, Vic
	South Grampians Shire	Load capacity testing & inspection on a steel and timber composite bridge, Vic
	North Grampians Shire	Load capacity testing & inspection on 3 steel and timber composite bridges, Vic
	Colac Otway Shire	Load capacity testing & inspection on 4 composite steel and timber bridges, Vic
Year	Client	Location
2002		
	Campaspe Shire	Capacity test on timber composite Normans Bridge, Pyramid Hill, Vic
	Baw Baw Shire	Capacity test on 2 timber composite bridges, single & multispan, Gippsland, Vic
	Campaspe Shire	Capacity test on a timber bridge, Gunbower Bridge near Rochester, Vic
	Wellington Shire	Capacity testing on two multi span reinforced concrete bridges and one 400m
		Prestressed beam bridge, Gippsland, Vic
	Delotite Shire	Load capacity testing & inspection on single span timber bridge, Vic
Year	Client	Location
2001	Campsape Shire	Capacity testing on a Monash designed bridge at Strathalen, Vic
2000	Alpine Shire	Capacity testing of 2 bridges, single & multi span, near Bright, Vic
1990 to	South East Asia	150 steel truss bridges on the Tanah Abang to Merak Railway upgrade
1999		with spans from 10 to 40 metres, predominantly 20 to 30 metre spans
		over large rivers.
	RTA, NSW	Bawden Bridge, Grafton. Wrought Iron truss historic bridge, 35m span
		McClean Bridge, Grafton. Composite wrought iron & timber bridge
		with large spans, NSW
	Remedial Engineering	Morrell Bridge, Melbourne, historic bridge, Vic