

AUSTRALIAN DBTS TESTS™ PROJECTS

Listed below are some of our recent projects using the "DBTS Testing" System.
These are generally our Australian Projects

Note: Marine projects in red.

Year	Client	Location
2019		
	Kane Constructions	Full Level 3 testing of slabs at building at Collins St, Melbourne, Vic
	Vic Track	Full Level 3 testing of Chimney tower at Newport, Vic
	Kane Constructions	Covermeter survey to supplement slabs testing at Collins St, Melbourne, Vic
	Vertical Engineering	Testing of foundations for the wind turbine farm in South Australia
	Vic Track	Reverse engineering design Green St, Wangaratta, Vic
	Bendigo GCC	Full Level 3 testing of 5 bridges around Bendigo, Vic
	Vic Track	Propping & visual at Tarp Shed, Newport, Vic
	Doug McDonnell/Alia Hoy	Level 3 testing of columns/slabs at University of Melbourne
	Lendlease	Grout duct testing at Docklands, Vic
	Peninsular Health	Full Level 3 testing of columns/slabs at Warrigul Hospital, Vic
	Multiplex	Full Level 3 testing of columns/slabs at Melbourne Central
	Portico, Portsmouth, UK	Full Level 3 testing of jetty deck at Commercial Port, Portsmouth, UK
	RMS-NSW	Full Level 3 testing of Korns bridge, NSW
	Mulgoa Excavation	Full Level 3 testing of bridge in Mulgoa, NSW
	Bendigo GCC	Full Level 3 testing of 4 bridges around Bendigo, Vic
	Bendigo GCC	Full Level 2 testing of 6 bridges around Bendigo, Vic
	Narrabri Council	Full Level 3 testing of 3 long bridges, Narrabri, NSW
	Portsmouth City Council, UK	Full Level 3 testing of jetty deck at Camber Quay, Portsmouth, UK

Year	Client	Location
2018		
	Victrack	Full Level 3 Inspection of an Armco culvert bridge, Bacchus Marsh, Vic
	Loddon Shire	Full Level 3 Inspection of a timber composite bridge, Vic
	Bayside CC	Full Level 3 Inspection of an RC bridge, Vic
	Webber Design	Full Level 3 Inspection of building 508 City Rd, Vic
	Tasports	Full Level 3 Inspection of 400m long jetty, Hobart, Tas
	Bendigo GCC	Full Level 3 Inspection of 6 composite bridges, Vic
	I-Cubed	Full Level 3 Inspection of a timber bridge, Qld
	Coffs Harbour	Full Level 3 Inspection of 3 bridges, timbe & RC, NSW
	Victrack	Full Level 3 Inspection of 60m high chimney, Vic
	Museum Victoria	Full Level 3 Inspection of Immigration Museum, Vic
	Built	Full Level 3 Inspection of staircases, State Library, Vic
	BAE (Australia)	Full Level 3 Inspection of 4 jetties, 350m, Williamstown, Vic
	Webber Design	Full Level 3 Inspection of a building Salmon Street, Vic
	Victrack	Full Level 3 Inspection of a bridge at Rutherglen, Vic
	Webber Design	Full Level 3 Inspection of a building in Dorcas St, Vic
	Narranderra SC	Full Level 3 Inspection of an RC bridge, Vic
	Vert Engineering	Full Level 3 Inspection of a wind turbine tower, SA
	Gold Coast Casino	Full Level 3 Inspection of the GC Casino Park, Qld
	Yarra Ranges	Full Level 3 Inspection of cable stay bridge, Vic
	Aurecon	Full Level 3 Inspection of 5 balconies at Alfred Hospital. Vic
	Victrack	Full Level 3 Inspection of RC bridge, Vic
	Bendigo GCC	Full Level 3 Inspection of brick arch bridge, Vic

AUSTRALIAN DBTS TESTS™ PROJECTS

Raine and Horne	Full Level 3 Inspection of the Gold Coast Casino, Qld
Victrack	Full Level 3 Inspection of 3 brick arch bridges, Vic
TGM	Full Level 3 Inspection of the Ballarat Theatre, Vic
Bendigo GCC	Full Level 3 Inspection of 3 composite bridges, Vic
Moira Shire	Full Level 3 Inspection of a timber bridge, Vic

Total for 2018

Bridges 24 all types

Buildings- 9 buildings

Marine 750 metres

Miscellaneous- Wind turbines, Tower, Staircase & Balconies

Year	Client	Location
2017		
	Moira Shire	Full Level 3 Inspection of a timber bridge, Vic
	Tenterfield Shire	Full Level 3 Inspection of 17 no timber bridges. NSW
	Victrack	Full Level 3 Inspection of concrete & brick building. Vic
	Victrack	Full Level 3 Inspection of a composite bridge. Vic
	Tamara Shire	Full Level 3 Inspection of 2 concrete bridges. NSW
	Irwin Consult	Full Level 3 Inspection of the State library, Vic
	Bendigo GCC	Full Level 3 Inspection of 3 concrete bridges, Vic
	Hilltops SC	Full Level 3 Inspection of 14 bridges, for NSW future roads
	Lockhart SC	Full Level 3 Inspection of 11 bridges, for NSW future roads
	BAE UK	Full Level 3 Inspection with berthing for Blockhouse Jetty-800m UK
	BAE UK	Full Level 3 Inspection of two Historic buildings in Portsmouth. UK
	Woollondilly SC	Full Level 3 Inspection of 3 very large concrete bridges. NSW
	N Grampians SC	Full Level 3 Inspection of two composite bridges. Vic
	Irwinconsult	Floor testing of State Library Victoria. Vic
	GHD Cairns	Full Level 3 Inspection of a large timber bridge. Qld
	Hilltops SC	Full Level 3 Inspection of 14 no bridges. NSW
	Victrack	Full Level 3 Inspection of 13 brick arch bridges, near Bendigo, Vic
	Victrack	Full Level 3 Inspection of a timber bridge in Gippsland. Vic
	Melbourne University	Full level 3 Inspection of a high rise building. Vic
	Victrack	Full Level 3 Inspection of a shop in Hawthorn. Vic

Total for 2017

Marine

800 metres of Jetty at Portsmouth. UK

All Bridges

84 bridges of all types of structure'

Buildings

7 buildings, largest State Library, Vic

Year	Client	Location
2016		
	Tamworth RCC	Full Level 3 Inspection of 80 bridges for compliance for HML. NSW
	Victrack	Full Level 3 Inspection of six bridges for potential upgrades. Vic
	Weddin SC	Full Level 3 Inspection of a timber bridge. NSW

AUSTRALIAN DBTS TESTS™ PROJECTS

Bendigo GCC	Full Level 3 Inspection of 3 timber bridges. Vic
BAE UK	Full Level 3 Inspection of three jetties with a length of 1.2km, UK
BAE UK	Full Level 3 Inspection on Dock 14, Petrel Jetty, Dry Dock gates, Shell Jetty . Bollards- Shear and Victory jetties, portsmouth. UK
TMG	Full Level 3 Inspection on composite concrete & steel bridge. Vic
Bendigo GCC	Full Level 3 Inspection on Nolan St bridge, composite steel and concrete bridge. Vic
Mirvac	DBTS & Mod-Shock testing of a new 24 storey building, Docklands. Vic
Gwydir SC	Full Level 3 Inspection of 3 number concrete bridges. NSW
BAE Australia	Full Level 3 Inspection of 3 no jetties at Williamstown, Vic
Woolondilly SC	Full Level 3 Inspection of large concrete bridges +200m after flood damage. NSW
TGM	Full Level 3 Inspection of Heritage Concrete & Masonry bridge. Vic
Midcoast SC	Full Level 3 Inspection of 19 no timber bridges for NSW future projects
REROC	Full Level 3/4 Inspection of 33 no bridges for NSW future projects. NSW
Bendigo GCC	Full Level 3 inspections of 3 no timber bridges. Vic
MPV	Full level 3 Inspection of the Heritage State Library in Melbourne. Vic'

Total for 2016

Marine	1.2km of Jetty and 10 no docks & jetties.
Bridges NSW	109 bridges including timber, concrete and composite bridges.
Bridges Vic	15 bridges- timber, steel composites and concrete bridges.
Buildings	65 storeys on three major high rise and Heritage buildings
Future roads NSW	Part of the 109 bridges for NSW 102 bridges.

Year	Client	Location
2015	LendLease	Full Level 3 Inspection of the Collins St Extension, Docklands. Vic
	GHD	Full Level 3 Investigation of Bourke St Dock. Vic
	Colac Otway	Full Level 3 Inspection of 2 no timber bridges. Vic
	GHD	Full Level 3 Investigation of the berths at port Mackay, QLD
	BAE UK	Full investigation of serviceability & load capacity, Bolier House. UK
	West Wimmera Shire	Full Level 3 Investigation of 2 swimming pools for structural adequacy, Vic
	BAE UK	Full Level 3 Inspection of another 1km of the North Corner Jetty Portsmouth, UK
	Moira Shire	Full Level 3 Inspection of a timber composite bridge, Vic
	VicTrack	Full Level 3 Inspection on a concrete & steel composite bridge, Vic
	VicTrack	Full Level 3 Inspection of a heritage brick water tower, Vic
	Moira Shire	Full Level 3 Inspection of a timber & steel composite bridge, Vic
	Yarra Ranges Shire	Full Level 3 Inspection of a concrete & timber composite bridge, Vic
	VicTrack	Full Level 3 Inspection of a very long concrete & steel composite bridge, Vic
	VicTrack	Full Level 3 Inspection for safe loading of reinforced concrete slab, Vic
	VicTrack	Full Level 3 Inspection of a 300 metre footbridge, Vic
	Coolamon Shire	Full Level 3 Inspection of 3 composite bridges for Mass Limit Loadings, NSW

AUSTRALIAN DBTS TESTS™ PROJECTS

Woolondilly Shire	Full Level 3 Inspection of 180m long Blaxland bridge, NSW
VicTrack	Full Level 3 Inspection of 2 bridges damaged by truck, Daylesford, Vic
Cassowary Coast Council	Full Level 3 Inspection of three composite bridges, QLD
Yarra Ranges Shire	Full Level 3 Inspection of steel truss bridge, Vic

Year	Client	Location
2014		
	Horsham City Council	Full Level 3 & DBTS on Norton Creek Bridge, Vic
	Sydney Water	Full Level 3 & DBTS on Bargo River Bridge, NSW
	Bendigo City Council	Full Level 3 & DBTS on four timber bridges, Vic
	Weddin Shire Council	Full Level 3 & DBTS on a large concrete bridge, NSW
	BAE UK	Full Level 3 & DBTS for 2km of Jetties, Portsmouth, UK
	VicTrack	Full Level 3 & DBTS to Stawell Station exit bridge, Vic
	Coffs Harbour City Council	Full Level 3 & DBTS on two timber bridges, NSW
	Baw Baw Shire	Full Level 3 & DBTS on 13 composite bridges, Vic
	Gold Coast City Council	Full Level 3 & DBTS on 3 large & long concrete bridges, QLD
	Toowoomba City Council	Full Level 3 & DBTS of a large bus depot, QLD
	ADGE	Full Level 3 Inspection of building at 171 George St, Brisbane, QLD
	BAE Williamstown	Williamstown Utilities Building, full Level 3 inspection, Vic
	VicTrack	Full Level 3 Inspection of the Dimboola Station footbridge, Vic
	Tamworth Regional Council	Full Level 3 Inspection of 11 composite bridges, NSW
	Bendigo City Council	Full Level 3 Inspection of three timber bridges, Vic
	Baw Baw Shire	Full Level 3 Inspection of a timber/steel composite bridge, Vic
	BAE UK	Full Level 3 & DBTS on a further 2km of Jetties, Portsmouth, UK

Year	Client	Location
2013		
	Webber Design	DBTS testing of floor slabs at 570 Bourke St, Melbourne, Vic
	Irwinconsult	DBTS tests on floor slabs at Centerlink Building, Melbourne, Vic
	VicTrack	Full level 3 inspection & DBTS for three composite bridges, Vic
	Bendigo City Council	Full level 3 with DBTS for three composite bridges, Vic
	Webber Design	DBTS testing of floor slabs at Flockhart Building, Melbourne, Vic
	Tamworth Regional Council	Full level 3 inspection & DBTS for 20 bridges, Tamworth, NSW
	GHD Cairns	Full level 3 with DBTS on a composite bridge, Cairns, Qld
	Moyne Shire	Full level 3 with DBTS for 16 bridges, Warrnambool, Vic
	Gold Coast City Council	Full level 3 with DBTS for a timber bridge, Gold Coast, Qld
	Moyne Shire	Full level 3 with DBTS on 5 composite bridges, Vic
	Wagga Wagga City Council	Full level 3 with DBTS on the Eunony Bridge, NSW
	Robert Bird Group	DBTS testing of the floor slabs for Aldi store, Altona Gate, Vic
	Taree City Council	Full level 3 & DBTS on a large timber bridge after repairs, NSW
	Kingston City Council	Full level 3 with DBTS on two concrete bridges, Vic
	Paul Webber Design	Full level 3 with DBTS for new Aldi store, Reservoir, Vic

Year	Client	Location
2012		
	VicTrack	DBTS testing of roof support structures- 6 tests, Vic
	Gertrude Street	DBTS testing of a roof slab for reuse, Vic

AUSTRALIAN DBTS TESTS™ PROJECTS

VicTrack	Full level 3 inspection on a concrete bridge, Vic
Ararat City Council	DBTS to determine stability & voidage below a swimming pool, Vic
Forbes Shire	Retest of historic bridge after recommended repairs, Vic
Port Macquarie Hastings	Full level 3 inspection of Stingray Bridge for repair strategy, NSW
Colac Otway Shire	Full level 3 inspection of three composite bridges, Vic
GHD Cairns	Full level 3 inspection of Tully Falls Bridge, Qld
Boorowa Shire	Full level 3 inspection of a composite bridge, NSW
Coolamon Shire	Full level 3 inspection of two large composite bridges, NSW
AIM Building	DBTS of five floors for determining additional capacity, Vic
Austin Hospital	DBTS of two floor slabs for heavier loadings, Vic
Kingston City Council	DBTS of three bridges for serviceability, Vic
Laing O'Rourke	DBTS testing of slabs in a new building, Brisbane, Qld
BAE Williamstown	DBTS testing of timber/concrete wharf for Safe Additional Loads, Vic
Irwinconsult	DBTS testing of floor slabs at two large commercial buildings, Vic

Year	Client	Location
2011		
	Wagga Wagga City Council	Retest of two bridges after repairs, NSW
	Cassowary Coast Council	22 Bridges, full level 3 inspections after tropical cyclone "Yasi", Qld
	Loddon Shire	5 Bridges, full level 3 inspections after flooding, Vic
	South Gippsland Shire	2 Bridges, full level 3 inspections for rail trail, Vic
	Gold Coast City Council	4 concrete bridges, full level 3 inspections after floods, Qld
	Gunnedah Shire	13 Bridges, full level 3 inspections for load and integrity, NSW
	Gold Coast City Council	7 timber bridges, full level 3 inspections for loadings, Qld
	Colac Otway Shire	4 Bridges, full level 3 inspections for serviceability, Vic
	City of Greater Bendigo	2 bridge retests after repairs, Vic
	Wagga Wagga City Council	6 bridges tested after recommended repairs from prior inspections, NSW
	Tamworth Regional Council	21 bridges for full DBTS and recommendations after floods, including a historic Allan Truss Bridge, NSW
	Bonnaci Group	Testing of floor slabs at a Springvale Road factory, Vic
	City of Greater Bendigo	4 bridges for reinspection after initial testing over 5 years ago, Vic
	Wollondilly Shire Council	5 bridges for full DBTS, with recommendations for repairs, NSW
	Boorowa Shire	Large six span timber bridge with full DBTS, NSW

Year	Client	Location
2010		
	South Gippsland Shire	Full DBTS on timber/steel composite bridge, Vic
	Port of Rabaul	DBTS on deck to two large wharves, Rabaul, PNG
	South Gippsland Shire	Full level 3 inspections, plus design & supervision on bridge, Vic
	Baw Baw Shire	Full level 3 inspections on three composite bridges, Vic
	Department of Justice	Floor loadings for installation of new computers, Melbourne, Vic
	Wagga Wagga City Council	Full level 3 inspections on Brooklyn Lane bridge, NSW
	South Gippsland Shire	Re-checking 2 bridges for loading capacities, after desk top studies closed the bridges. We retested & now repaired for T-44 trucks, Vic
	Wagga Wagga City Council	Full level 3 inspections for 14 bridges after severe flooding, NSW
	Bendigo City Council	Full level 3 inspections for 4 bridges including Historic Arch, Vic
	South Gippsland Shire	Composite steel and concrete bridge, full level 3 inspection, Vic

AUSTRALIAN DBTS TESTS TM PROJECTS

Ararat Rural City Council	Level 3 testing of 8 bridges, steel, timber & concrete, Vic
South Gippsland Shire	Full inspection of bridge, design & supervision of repairs, Vic
VicTrack Access	Re-testing of large cast iron bridge after previous desk top study recommended new bridge. Bridge reopened after minor repairs, Vic
GHD Cairns	Third testing for Jubilee Bridge in Innisfail, bridge closed and new bridge to be constructed, Qld
VicTrack Access	Full level 3 inspection of 4 timber bridges, design & repair supervision, Vic
Wagga Wagga City Council	Full level 3 inspection of 7 composite steel & concrete bridge, NSW
Gunnedah Shire	Full level 3 inspection of timber composite bridge, NSW
Port Macquarie Hastings	Full level 3 inspection of 11 bridges, composite steel & timber, NSW
Port Macquarie Hastings	Full level 3 inspection of Historic Kindee Bridge, a unique timber suspension bridge, NSW
VicTrack Access	Full level 3 inspection, design & supervision of a timber bridge, Vic
Ararat Rural City Council	Full level 3 inspection of a bridge where an accident had occurred, with re-design recommendations, Vic
Harden Shire	Full level 3 inspection of 3 bridges from our results of our previous level 2 inspections, NSW
Forbes Shire	Full level 3 inspection of an Historic timber structure, NSW
South Gippsland Shire	Full level 3 inspection of a timber bridge, Vic
City of Greater Bendigo	Full level 3 inspection of 3 timber bridges for rail trail, Vic
Wagga Wagga City Council	Full level 3 inspection of 20 composite bridges after severe flooding, NSW
VicTrack Access	Full level 3 inspection and design & supervision of repairs to 3 bridges, Vic
Roaring Forties	The use of DBTS system to determine serviceability of seven large concrete bases for Wind Turbines, Smithton, TAS

Year	Client	Location
2009		
	Victrack	Structural Testing of Historic Merri River bridge at Dennington, Vic
	Wagga Wagga City Council	Consultant for rescue for partially failed 1895 AlanTr uss Bridge (Hampden Bridge). Successfully restored & now to be used as a Rail Trail, NSW
	Armidale Dumaresq Shire	Testing of two composite bridges for load rating, etc, NSW
	City of Greater Bendigo	Five bridges with various construction, full DBTS, Vic
	VicTrack	Full level 3 inspection & DBTS of 10 bridges, all timber composites & 5 requiring repair specifications & full site control of the repairs, Vic
	Colac Otway Shire	Full DBTS with various constructions but mainly timber bridges, Vic
	City of Coffs Harbour	Repair strategy for all timber bridges, NSW
	Wagga Wagga City Council	Kapooka Historic Rail Arch Bridge, full level 3 with discussions with various parties for the repairs to the bridge, NSW
	Wellington Shire	Full level 3 inspection of the Lake Glenmaggie Historically listed bridge over Lake Glenmaggie. Preparation of options for repairs for the timber truss section of the bridge, Vic
	GHD Cairns	Retesting of Historic Jubilee bridge, Innisfail to determine rate of loss of load capacity after initial full DBTS testing of bridge in 2003, Qld
	Greater Taree Council	Full DBTS of 7 bridges, all composite timber bridges, NSW
	Colac Otway Shire	Re-testing of two timber bridges after repairs for load testing, Vic
	South Gippsland Shire	Full DBTS on 3 composites concrete/steel bridges, Vic
	Port Macquarie Hastings	Full DBTS on 10 bridges, various timber & timber composites, NSW

AUSTRALIAN DBTS TESTS™ PROJECTS

VicTrack	DBTS on structural adequacy of a factory brick chimney, Bendigo, Vic
Loddon Shire	Full DBTS on 5 bridges, timber composites & concrete, Vic
South Adelaide Hills	Full DBTS on a steel/concrete composite bridge, SA
Greater Taree Council	Full DBTS on a timber/steel composite bridge, NSW
VicTrack	Full DBTS on 4 timber/steel composite bridges, Vic
North Grampians Shire	Full DBTS on 15 bridges, timber, steel & concrete, Vic
Wellington Shire	Full DBTS on Glenmaggie bridge for Heritage, Vic
Greater Taree Council	Re-testing timber truss bridge after repairs, NSW

Year	Client	Location
2008		
	Moyne Shire	Inspection and testing of five bridges, Vic
	David Jones	Testing of six floors by DBTS for reverse Engineering with over 200 DBTS tests performed for the floor capacities. David Jones Store, Bourke St Mall, Melbourne, Vic
	Saracen Properties	Testing of five floors of a multi storey car-park for reverse Engineering for extension of the car park, Perth, WA
	VicTrack	Inspection and testing of a rail overbridge, Huntly, Vic
	City of Greater Bendigo	Inspection and testing of three bridges, Vic
	Wagga Wagga City Council	Inspection and testing of seven span historic bridge, NSW
	VicTrack	Inspection and testing of seven timber bridges including design, production of drawings and project supervision, VIC
	Wagga Wagga City Council	Inspection and testing of eight span concrete bridge, NSW
	Bovis Lendlease	Testing floor slabs for redevelopment, Valley Metro, Qld
	Jones Lang Lasalle	Testing floor slabs for redevelopment, Mornington, Vic
	City of Coffs Harbour	Inspection & testing of a five span bridge, Coffs Harbour, NSW
	Inverall Shire	Inspection & testing of three multi span bridges, Inverall, NSW
	Narrabri Shire	Inspection, testing & repair requirements of bridges, Narrabri, NSW
	Muswellbrook Council	Inspection & testing of 4 multispan bridges, Muswellbrook, NSW
	City of Coffs Harbour	Level 3 testing of one bridge & Level 2.5 testing of 5 bridges, NSW
	Baw Baw Shire	Inspection and testing of three bridges, Baw Baw, Vic
	First State Group	Testing of floor slabs for redevelopment, Mornington, Vic
	Oberon Shire	Inspection and testing of one bridge, Oberon, NSW
	City of Greater Bendigo	Inspection and testing of four multi span bridges, Bendigo, Vic
	Melton Shire	Inspection and testing of a bridge for CFA requirements, Melton, Vic

Year	Client	Location
2007		
	Central Goldfields Shire	DBTS testing of 5 bridges, timber, steel & concrete, Vic
	Armidale Dumaresq Shire	Inspection and testing of five bridges, all types, NSW
	Gundagai Shire	Inspection and testing of Historic Bridge, NSW
	Yarra Ranges Council	Inspection and testing of two timber bridges, Vic
	Moyne Shire	Inspection and testing with DBTS of five bridges, Vic
	Weddin Shire	Inspection and testing of an Historic Bridge, NSW
	Nambucca Heads Shire	Inspection and testing of an Historic Bridge, NSW
	Mitchell Shire	Inspection and testing of two critical bridges, Vic

AUSTRALIAN DBTS TESTS™ PROJECTS

City of Greater Bendigo	Inspection and testing of four bridges in critical condition, Vic
Colac Otway Shire	Inspection and testing of three bridges, Vic
City of Greater Bendigo	Inspection and testing of four bridges, Vic
Wellington Shire	DBTS load rating of bridges previously inspected using our 2.5 Inspection system, nine bridges tested, Vic
Wellington Shire	Inspection & load testing of six bridges due to flood damage, Vic
Urana Shire	Inspection and testing of seven bridges, NSW
First State Colonial	DBTS load testing of all spans over eight floors & over 200 DBTS tests carried out at the Myer Store, Bourke St, Melbourne, Vic
Moyne Shire	Inspection and testing of four bridges, Vic
Wellington Shire	Inspection and testing of four flood damaged bridges, Vic
Yarra Ranges Shire	Load rating of a single timber bridge, Vic
Wellington Shire	Inspection and load testing of timber bridge, Vic
Gloucester City Council	Inspection and testing of an Historic Bridge, NSW
City of Coffs Harbour	Inspection and load testing of three bridges, NSW
Baw Baw Shire	Inspection and testing of eight bridges of various constructions, Vic
City of Greater Bendigo	Inspection and testing of three bridges, Vic

Year	Client	Location
2006		
	Wellington Shire	22 bridge inspections using the 2.5 inspection system, Vic
	City of Coffs Harbour	Full DBTS testing of an Historic Timber Bridge, NSW
	Wellington Shire	Full DBTS and specification for repairs of Wheelers bridge, an historic Monash designed bridge & concrete arch, Vic
	Moorabool Shire	Full DBTS testing of six bridges of mixed composites, Vic
	South Gippsland Shire	Testing of two timber bridges with critical loading requirements, Vic
	City of Coffs Harbour	Retesting of bridge with DBTS after our recommended repairs, NSW
	Tamworth Regional Council	Full DBTS test of five bridges with mixed composites, NSW
	Wagga Wagga City Council	Full DBTS test of seven mixed composite bridges, NSW
	Gundagai Shire	Full DBTS test of Historic bridge with critical loadings, NSW
	Kyogle Council	Full DBTS test five timber bridges for safety of fire trucks, NSW
	Tenterfield Shire	Full DBTS test on bridge structure, critical for school bus, NSW
	Taree City Council	DBTS inspection of two timber bridges with specifications for repairs. Retested after repairs, now suitable for T-44 loadings, NSW
	Moyne Shire	Specifications for three bridges with site supervision, Vic
	Moyne Shire	Full DBTS test of five bridges for safe loadings of timber trucks, Vic
	Moira Shire	Full DBTS test of Historic Hancocks Bridge, Vic
	Tamworth Regional Council	Testing of 8 bridges for repairs rather than replacement due to lack of funding, NSW
	Wellington Shire	Completion of a total of 95 bridges with a 2.5 inspections, Vic
	Murrumbidgee Irrigation	Full DBTS test of recent precast concrete bridge with cracking, NSW
	City of Greater Bendigo	Full DBTS test of 7 bridges of mixed construction, Vic
	Wagga Wagga City Council	Full DBTS test of an 1895 Allan Truss Hampden Bridge after partial failure & specification of repairs, NSW
	City of Coffs Harbour	Full DBTS test of two very long timber bridges, NSW
	Moyne Shire	Full DBTS test of 12 bridges for safe passage of timber trucks, Vic
	Gloucester City Council	Full DBTS test of a 50m timber/steel composite bridge, NSW

AUSTRALIAN DBTS TESTS TM PROJECTS

City of Coffs Harbour DBTS test of jetty for safety of large pedestrian traffic usage with power boat racing under the jetty, NSW
 Taree City Council Testing of long timber bridge, upgrade for T-44 usage, NSW

Year	Client	Location
2005		
	Central Goldfields Shire	Testing of six composite bridges by DBTS, Vic
	Moyne Shire	Testing of five composite bridges by DBTS, Vic
	Moyne Shire	DBTS testing of concrete bridge, plus foundations of timber bridge, Vic
	Central Goldfields Shire	Specifications for two bridge repairs, Vic
	Pyrenees Shire	DBTS testing of three composite bridges, Vic
	Palerang Council	Testing of two multi span bridges near the ACT, NSW
	Tenterfield Shire	DBTS testing of two timber bridges, NSW
	Wagga Wagga City Council	DBTS testing of six timber & timber composite bridges, NSW
	Central Goldfields Shire	Advisor to Council on cost effectiveness of repairs to 2 bridges, NSW
	Moira Shire	Full investigation of five composite steel & timber bridges, Vic
	Ballina Shire	Investigation of an 8 span composite steel & timber bridge, NSW
	Moira Shire	Advise on urgent repairs to two bridges closed to traffic, Vic
	Colac Otway Shire	Testing of 9 span timber bridge over a river after partial repairs, Vic
	Corangamite Shire	Testing to determine load rating of concrete bridge, Vic
	GHD Canberra	Determination of load capacity of foundations, ACT
	Wellington Shire	Investigation of 20 bridges using our Level 2.5 inspections, Vic
	Baw Baw Shire	Testing of three composite steel & timber bridges, Vic
	City of Coffs Harbour	Testing of three composite steel & timber bridges, NSW
	Tamworth Regional Council	Testing of timber bridges, NSW
	Armidale Dumaresq Shire	Testing of three timber bridges, NSW
	Ararat Rural City Council	Testing of two composite steel & timber bridges, Vic
	Moyne Shire	Testing of 13 composite steel, timber concrete & masonry bridges, Vic

Year	Client	Location
2004		
	Alpine Shire	Testing of three suspension bridges, Vic
	Central Goldfields Shire	Testing of six composite & reinforced concrete bridges, Vic
	Wellington Shire	Testing of four composite & reinforced concrete bridges, Vic
	South Gippsland Shire	Testing of six composite & reinforced concrete bridges, Vic
	Wellington Shire	One timber bridge test and repair specifications for six bridges, Vic
	South Gippsland Shire	Testing of two reinforced concrete bridges, Vic
	GHD Cairns	Testing of 220m long composite steel & concrete bridge, Barron Gorge, Cairns, Qld
	Baw Baw Shire	Investigation of 3 composite concrete, steel & timber bridges, Moe, Vic

Year	Client	Location
2003		
	Gippsland Ports	Deck capacity of 500m jetty at Port Welshpool, Vic
	South Gippsland Shire	Testing of multi span composite bridge at Agnes, Gippsland, Vic
	GHD Cairns	Testing of Jubilee Historic reinforced arch bridge, Innisfail, Qld
	Hepburn Shire	Investigation of 2 timber composite bridges, Clunes & Leonards, Vic

AUSTRALIAN DBTS TESTS™ PROJECTS

City of Coffs Harbour	Testing 3 reinforced concrete & one reinforced arch bridge, NSW
Wellington Shire	Prospect bridge, a reinforced concrete bridge, Vic
Naracoorte Lucindale Council	Testing a Monash design reinforced concrete bridge, SA
Townsville Port Authority	Testing of approach bridge, part of Berth1, Townsville Port, Qld
Hindmarsh Shire	Testing six reinforced concrete bridges & one timber bridge, Vic
South Gippsland Shire	Testing of single span timber bridge, Vic
Pyrenees Shire	Test on 6 composite steel/timber bridges and one concrete bridge, Vic
West Wimmera Shire	Investigation on composite timber bridge, Vic
GHD Cairns	Investigation on suspended swimming pool, Reef Hotel, Cairns, Qld
Baw Baw Shire	Test on three composite steel & timber bridges, Vic
South Gippsland Shire	Investigation on tree damaged concrete bridge, Vic
South Grampians Shire	Test on a steel and timber composite bridge, Vic
North Grampians Shire	Tests on three steel and timber composite bridges, Vic
Colac Otway Shire	Test on four composite steel and timber bridges, Vic

Year	Client	Location
2002		
	Campaspe Shire	Test on timber composite Normans Bridge, Pyramid Hill, Vic
	Baw Baw Shire	Test on 2 timber composite bridges, single & multispan, Gippsland, Vic
	Campaspe Shire	Test on a timber bridge, Gunbower Bridge near Rochester, Vic
	Mirvac	Deck capacity of Princess Pier, Melbourne, Vic
	Wellington Shire	Testing on two multi span reinforced concrete bridges and one 400m Prestressed beam bridge, Gippsland, Vic
	Delotite Shire	Testing on single span timber bridge, Vic

Year	Client	Location
2001	Campaspe Shire	Testing on a Monash designed bridge at Strathalen, Vic
2000	Alpine Shire	Testing of 2 bridges, single & multi span, near Bright, Vic
1990 to 1999	South East Asia	150 steel truss bridges on the Tanah Abang to Merak Railway upgrade with spans from 10 to 40 metres, predominantly 20 to 30 metre spans over large rivers.
	RTA, NSW	Bawden Bridge, Grafton. Wrought Iron truss historic bridge, 35m span McClellan Bridge, Grafton. Composite wrought iron & timber bridge with large spans, NSW
	Remedial Engineering	Morrell Bridge, Melbourne, historic bridge, Vic